

	Type	L #	Hits	Search Text	Dbs	Time Stamp	Comments	Error Definition	Errors
1	IS&R	L1	999	(340/442,443,445).CCLS.	US-PGPUB; USPAT	2005/03/16 10:26			
2	IS&R	L2	1201	(73/146).CCLS.	US-PGPUB; USPAT	2005/03/16 10:27			
3	BRS	L3	2827	(tire\$1 near\$3 (within into inside interior)).ab,ti,clm.	US-PGPUB; USPAT	2005/03/16 10:28			
4	BRS	L4	416	3 near\$10 (sensor\$1 detector\$1 transducer\$1 probe\$1 contact\$1 switch\$2).ab,ti,clm.	US-PGPUB; USPAT	2005/03/16 11:02			
5	BRS	L5	156	(1 2) and 4	US-PGPUB; USPAT	2005/03/16 10:40			
6	BRS	L8	3	5 and push\$1button	US-PGPUB; USPAT	2005/03/16 10:38			
7	BRS	L10	171061	spring\$1 near\$10 (sensor\$1 detector\$1 transducer\$1 probe\$1 contact\$1 switch\$2)	US-PGPUB; USPAT	2005/03/16 11:03			
8	BRS	L11	31	5 and 10	US-PGPUB; USPAT	2005/03/16 10:38			
9	BRS	L17	209	(1 2) and 10	US-PGPUB; USPAT	2005/03/16 11:03			
10	BRS	L18	123378	spring\$1 near\$5 (sensor\$1 detector\$1 transducer\$1 probe\$1 contact\$1 switch\$2)	US-PGPUB; USPAT	2005/03/16 11:03			
11	BRS	L19	158	(1 2) and 18	US-PGPUB; USPAT	2005/03/16 11:06			
12	BRS	L20	125	5 not 11	US-PGPUB; USPAT	2005/03/16 11:05			
13	BRS	L21	14168	(hang\$1 hanging dangl\$3 suspend\$3) near\$5 (sensor\$1 detector\$1 transducer\$1 probe\$1 contact\$1 switch\$2)	US-PGPUB; USPAT	2005/03/16 11:06			
14	BRS	L22	16	(1 2) and 21	US-PGPUB; USPAT	2005/03/16 11:06			